

- 1. Heavy Load Capacity
- 2. Self Tracking Belt Zinc Coated Steel
- 3. Heavy Duty Manganese Steel Tracks
- 4. Ball Bearing Load Rollers
- 5. Easy To Assemble 10' Long Welded Sections
- 6. Internal Bracing For Permanent Square Frame

- 7. Heavy Duty Reinforcement Of Belt Sections
- 8. Minimum Gap Between Belt And Frame For Safety
- 9. Clean, Safe Full Closure
- 10. Smooth Non-Tear Belt Easy On/Off Loading
- 11. Smooth Rounded Edges Minimum Gap
- 12. Tubular Legs, Adjustable Feet On 10' Centers